



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX Complete: Exploration:

Inspection Date & Time: 1/12/2001 / 8:30 AM- 1 PM

Date of Last Inspection: 12/12 & 15/2000

PGL
by
SQ

Mine Name: Trail Mountain Mine County: Emery Permit Number: 6009
 Permittee and/or Operator's Name: PacifiCorp
 Business Address: P.O. Box 310, Huntington, Utah 84528
 Type of Mining Activity: Underground XXX Surface Prep. Plant Other
 Company Official(s): Mr. Dennis Oakley, Mr. Rick Boyle, surface foreman
 State Official(s): Peter Hess Federal Official(s): None
 Weather Conditions: Clear, sunny; mid 40's Fahrenheit
 Existing Acreage: Permitted 4178 Disturbed 10.7 Regraded Seeded
 Status: Active XXX

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4 th Quarter- April, May, June)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/009

DATE OF INSPECTION: 1/10/2001

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The mine site sediment pond contained frozen snow melt; the elevation of same was well below the discharge level. There were no problems noted with the sediment pond.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The B.T.C.A. area located at the north end of the parking lot was inspected. The silt fence required a minor repair which was promptly made by Mr. Oakley. No other problems were noted.

4D. HYDROLOGIC BALANCE: WATER MONITORING

Water monitoring information for the third quarter of 2000 for the Energy West Mines was submitted to the UDNR/OGM/SLO on December 14, 2000. A review of the submitted information relative to the Trail Mountain Mine was conducted during today's partial inspection.

Springs T-6, T-8, T-9, T-10, and T-14 had reportable flows, where T-14A, T-15, and T-16 were all dry in September. All sites having flows had reportable quantities for the required operational analytical parameters.

Stream monitoring locations SW-1, SW-2, SW-3, CCC01, and T-19 were all monitored for the required field parameters as well as the required operational analytical parameters on September 12, 2000. CCC01 was monitored for field parameters only, as is required by the approved mining and reclamation plan. All stream analyses had cation/anion balances within the acceptable error range.

Site T-18 (Oliphant Mine mine water discharge) in Straight Canyon was monitored on September 12, 2000 for all required operational field parameters as well as required analytical parameters. All lab parameters showed reportable results, with an acceptable cation/anion balance.

Trail Mountain well TM-1B was monitored on September 11, 2000. No problems were noted with the ground water analysis for the September 11th sample. A cation/anion balance of +1.6% was reported.

The in-mine ground water monitoring location designated as UG-3 was sampled on October 3, 2000 for the third quarter. All required parameters showed reportable results; the cation/anion balance reported was -3.4%.

Inspector's Signature: _____

Peter Hess #46

Date: January 11, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James Fulton, OSM
Chuck Semborski, PacifiCorp
Price Field office

O:\015009.TMT\Compliance\2001\p_0110.wpd